


PDCA DIAGRAM

01 PLAN

Undersand the problem and arrive at a root cause as a team.

O4 ACT (ADJUST)

Modify and Act as necessary.



02 DO

Implement the Fix/
Imporvement.

03 CHECK

Monitor performance.

Does it work?

findleansolutions.com